

2.21Z 13 MAY 1965

S E C R E T

DIRNSA, OGCEN, SAFSS, SAVSP, AFS30 SSD

SSO SAN FRANCISCO

ROUTINE

NRO Review Completed as Redacted.

IN 08125

FOR 0000Z 20 MAY 1965

S E C R E T [REDACTED] THIS IS A BYECOM MESSAGE HANDLE VIA

25X1

BYEMAN CHANNELS ONLY SFN [REDACTED]

25X1

FOR BCO'S:

SAFSS(PENTAGON) FOR [REDACTED]

SAFSP FOR [REDACTED]

DIRNSA FOR [REDACTED]

25X1

SSD FOR [REDACTED]

OGCEN FOR [REDACTED]

25X1

FINAL MESSAGE REPORT [REDACTED]

1. ALL DATA FROM THIS MISSION HAVE BEEN RECEIVED. WITH

THE EXCEPTION OF UNKNOWN ACTIVITY NOTED ON [REDACTED]

25X1

NO SIGNALS OF INTEREST WERE INTERCEPTED. THE

WAS NOT INTERCEPTED DURING THIS MISSION. THE

FUNCTIONED PROPERLY DURING THE ENTIRE MISSION LIFE WHICH

WAS PREMATURELY TERMINATED AFTER [REDACTED]

BECAUSE OF [REDACTED]

25X1

FAILURE IN THE [REDACTED] THE SCHEDULED LIFE WAS [REDACTED]

25X1

2. THE ACTIVITY NOTED ON [REDACTED]

OCCURRED AS THE VEHICLE

25X1

PASSED OVER THE [REDACTED] THE

INTERCEPT CONSISTED OF VERY [REDACTED]

25X1

AND A FREQUENCY OF [REDACTED]

APPROXIMATELY [REDACTED]

25X1

S E C R E T

(CONT-)

PAGE TWO

S E C R E T

IN 88125

[REDACTED] 25X1
MEASURED AT THE RECEIVER. TYPICAL [REDACTED]

[REDACTED] THE IRREGULAR CHARACTERISTICS OF THE INTERCEPT AND ITS REL- 25X1
ATIVELY LOW AMPLITUDE INDICATE THAT THE [REDACTED] 25X1

[REDACTED] DETAILS OF THE INTERCEPT WILL
BE CONTAINED IN THE HARD COPY FINAL REPORT.

END OF MESSAGE

S E C R E T